

Work Order:

TBD

Date of Issue: 22-Dec-2022

444						
W/O Category	Additional Line Check		Station	Schedule Start	Schedule Final	
Due Maintenance			GVA	TBD		
Aircraft: Falcon 2000	MSN:	TFLB/No	A/C Total Hours	A/C Total Cycles	Date of Compliance	Time(UTC)
LZ - 00I	123					

Nº	Reason	Description	Signature	Family Name
1	SPAO-SAO F2000 AMP /Issue 7 /Rev. 0 /Feb. 2022	To be performed #1 Engine and #2 Engine 400 hours Routine Inspection (i.a.w. LMM CFE738-1-1B, 05-21-00 Engine Inspection Program, CAMP Task code: 057115)		
2	SPAO-SAO F2000 AMP /Issue 7 /Rev. 0 /Feb. 2022	To be performed #1 Engine and #2 Engine 600 hours Minor Inspection (i.a.w. LMM CFE738-1-1B, 05-21-00 Engine Inspection Program, CAMP Task code: 057120)		
3	SPAO-SAO F2000 AMP /Issue 7 /Rev. 0 /Feb. 2022	To be performed Replacement of the LH MLG OUTBOARD BRAKE (pos. #1) (as per AMM Task 32-44-17-900-801-01)		
4	SPAO-SAO F2000 AMP /Issue 7 /Rev. 0 /Feb. 2022	To be performed Replacement of the Spare #1 and Spare #2 MLG WHEEL TIRES (as per AMM Task 32-44-13-900-801; Wheel SDI as per F2000 AMM included) (MLG Wheel SN: 01700 and F234)		
5	SPAO-SAO F2000 AMP /Issue 7 /Rev. 0 /Feb. 2022	To be performed LUBRICATION OF THE MAIN LANDING GEARS (MLG) AND MLG DOORS - LH/RH (as per AMM Task 32-10-00-640-801)		
6	SPAO-SAO F2000 AMP /Issue 7 /Rev. 0 /Feb. 2022	To be performed LUBRICATION OF THE NOSE LANDING GEAR (NLG) AND NLG DOORS (as per AMM Task 32-20-00-640-801)		
7	SPAO-SAO F2000 AMP /Issue 7 /Rev. 0 /Feb. 2022	To be performed STERILIZATION OF THE POTABLE WATER SYSTEM (as per AMM Task 38-10-00-670-801)		

	IF A TASK CARDS HAS NOT BEEN PERFORMED , GIVE REASONS FOR DEFERS:					
Nº	Task Card:	Reason for defer	Next Due	Signature	Family Name	

Attached WP	Attached KIT List	Attached Form 1	Attached Report	Attached Another Doc.
□ YES □ NO	□ YES □ NO	☐ YES ☐ NO	☐ YES ☐ NO	☐ YES ☐ NO
QTY.	QTY.	QTY.	QTY.	QTY.